

Fri May 17 11:30:44 EDT 2013

Warranty Vehicle Inquiry

2197886

CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2013 BMW of North America, LLC

Vehicle Data

VIN: WBSAK0307J2197886

Chassis Number: 2197886

Line Make: 01 - BMW

Model Year: 1988

AG Model Code/Desc: 1003 - M3/2

NA Model Code/Desc: 8821 - M3

Exterior Trim Code: 203 - SALMON SILVER

Interior Color Code: 0203 - BLACK LEATHER

MSRP: \$35,305.00

Davis #: N/A

TCU MIN:

Vehicle Production Date: 1988/02

Motor Type: S14

Platform/Engineering Series: E30

Wholesale Center ID/Loc: 05095-01

Wholesale Date: 05/16/1988

Retail Center ID/Loc: 05095-01

Retail Date: 08/10/1988

In-Service Date: 08/10/1988

New Vehicle Warranty Info

No Coverage As Of: 08/10/1988

Expiration Mileage:

NO OPEN CAMPAIGNS

Option Information

Code	Description	Code	Description
0100	Usable load increase	0401	steel power sunroof
0410	POWER WINDOWS 2 DR	0530	Manual climate control
0540	Cruise Control	0551	ON-BOARD COMPUTER
0675	STEREO SOUND SYSTEM	0900	ANTI-THEFT IMMOBILIZER
0947	PIONEER ANTI THEFT RADIO		

Chassis Number : 2197886

Customer Information

Name (First/Last): MS. SUSAN Y KLEBOLD
Address: 9351 S COUGAR RD
LITTLETON CO 80127-5115 UNITED STATES

Repair History (Claims)

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
05042	01	144060	11/11/2004	91094	10/15/2004	11/11/2004	N/A	10,320	5131004100	Windshield poorly adapted/fitted
05042	01	545820	00/00/0000	9721	08/18/2000	00/00/0000	N/A	214,037	0017010500	SIB #17-04-93 (3775) RECALL 93V-015 COOLANT SYSTEM E30 (M3)

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2013 BMW of North America, LLC